UNCLASSIFIED

AD NUMBER AD392694 CLASSIFICATION CHANGES TO: UNCLASSIFIED FROM: CONFIDENTIAL LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;
Administrative/Operational Use; 15 MAY 1966.
Other requests shall be referred to Office of the Adjutant General (Army), Washington DC 20310.

AUTHORITY

AGO ltr 29 Apr 1980 ; AGO ltr 29 Apr 1980

THIS REPORT HAS BEEN DELIMITED AND CLEARED FOR PUBLIC RELEASE UNDER DOD DIRECTIVE 5200.20 AND NO RESTRICTIONS ARE IMPOSED UPON ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

SECURITY MARKING

The classified or limited status of this report applies to each page, unless otherwise marked.

Separate page printouts MUST be marked accordingly.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.



DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

IN REPLY REFER TO

AGAM-P (M) (23 Aug 68) FOR OT RD 682185

6 September 1968

SUBJECT: Operational Report - Lessons Learned, Headquarters, 307th Combat Aviation Battalion, Period Ending 30 April 1968 (U)

SEE DISTRIBUTION

S

1. Subject report is forwarded for review and evaluation in accordance with paragraph 5b, AR 525-15. Evaluations and corrective actions should be reported to ACSFOR OT RD, Operational Reports Branch, within 90 days of receipt of covering letter.

2. Information contained in this report is provided to insure that the Army realizes current benefits from lessons learned during recent operations.

Program is readily available on a continuous basis, a cumulative Lessons Learned Index containing alphabetical listings of items appearing in the reports is compiled and distributed periodically. Recipients of the attached report are encouraged to recommend items from it for inclusion in the Index by completing and returning the self-addressed form provided at the end of this report.

at the end of this report.

BY ORDER OF THE SECRETARY OF THE ARMY:

1 Incl

KENNETH G. WICKHAM
Major General, USA

The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

Commandants

US Army Command and General Staff College

US Army Air Defense School

US Army Armor School

US Army Artillery and Missile School

US Army Aviation School

US Army Engineer School

US Army Infantry School

US Army Missile and Munitions School

SEP 80 1880

Regraded unclassified when separated from classified inclosure.

CONFIDENTIAL

Deficase of the United Junios within the merming the Main Espionege Laws, Illie 15, U. S. C., Section 186 and Milts transmission on the revalation of its overtents in manner to se unauthorized poracial is prehibited by less

Copies furnished: Office, Chief of Staff, US Army Deputy Chiefs of Staff Chief of Engineers Chief of Research and Development Assistant Chiefs of Staff Research Analysis Corporation OSD(SA), Assistant for Southeast Asia Forces Director, Weapons Systems Evaluation Group Defense Documentation Center Security Officer, Hudson Institute USAF Air Ground Operations School Documents Control Officer, Bell Aero Systems Co. Commanding Generals

- US Army Weapons Command
- US Army Materiel Command
- US Army Flight Training Center

Commanding Officers

- US Army Limited War Laboratory
- US Army Logistics, Doctrine Systems & Readiness Agency
- US Army Aviation Test Activity
- 307th Combat Aviation Battalion

DEPARTMENT OF THE ARMY HEADQUARTERS, 307TH COMBAT AVIATION (PHANTOM) BATTALION APO San Francisco 96296

AVBN-P

15 May 1968

SUBJECT: Operational Report of 307th Combat Aviation (Phantom) Battalion for Period Ending 30 April 1968, RCS CSFOR-65 (RI)

SEE DISTRIBUTION

1. Section 1. Operations: Significant Activities.

- a. (U) Mission: To provide command, control, staff planning, administrative and pathfinder support for the 199th and 221st Reconnaissance Airplane Companies, the 235th Armed Helicopter Company, the 244th Surveillance Airplane Company and be prepared to exercise operational control for additional aviation units that may be assigned or attached. Specifically, the battalien must provide aerial fire support, aerial observation, reconnaissance, surveillance and target acquisition suppert for the Republic of Vietnam (ARVN) IV Corps.
- b. (U) Organization: During the reporting period, the 307th Combat Aviation Battalion consisted of the following units with attachments:
- (!) (U) Headquarters and Headquarters Company 307th Combat Aviation Battalion and the 52nd Quartermaster Detachment attached stationed at Scc Trang, RVN (APO San Francisco 96296).
- (2) (U) The 199th Reconnaissance Airplane Company (0-1) stationed at Vinh Long, RVN (APO San Francisco 96357).
- (3) (U) The 221st Reconnaissance Airplane Company (0-1) with the 325th Signal Detachment (RL) attached and stationed at Soc Trang, RVN (APO San Francisco 96296).
- (4) (U) The 235th Armed Helicopter Company with the 608th Transportation Detachment (KD) and the 190th Signal Detachment (RL) attached and stationed at Can Tho, RVN (APO San Francisco 96215).
- (5) (U) The 244th Surveillance Airplane Company with the 502nd Transportation Detachment (KD) and the 537th Signal Detachment (RL & RX) attached and stationed at Can Tho, RVN (APO San Francisco 96215).

(See Organization and Stationing Chart, Incl 1)

CONFIDENTIAL

DOWNGRADED AT 3 YEAR INTERVALS: DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

FOROTRO 682185

c. Command Group Personnel:

- (1) (U) The 307th Combat Aviation Battalion had relatively few changes in the command group and the principal staff positions did not change during the reporting period. It is significant that the battalion had an executive officer for only 50 days of the reporting period and at present does not have an executive officer assigned. The battalion did not have an aviation maintenance officer for 41 days of the reporting period and does not have one assigned at the present time. This shortage of a special staff officer results in a severe handicap to this battalion in committing its resources because of the lack of proper evaluation of aircraft maintenance in the overall planning for operations. The frequent and short tenure of Aircraft Maintenance and Safety Officers precluded the development of adequate and viable maintenance and safety programs. The shortage of junior officers and warrant officers on the staff limited the primary staff capabilities to merely sustaining operations
 - (2) (C) Composition of Battalion Command Group:

Position	Rank	Name	<u>sn</u>	Assigned	Released
Commander Exec Off	tac tac	Charles F Hutchine Floyd O Eberhard	07705 3 088666	21 Dec 67 29 Feb 68	N/A 19 Apr 68
S-1	MAJ	Cornell L Ullman	05704892	10 Nov 67	N/A
S-2	iaj	Curtis J Herrick	090064	23 Jan 68	N/A
S-3	MAJ	Joe D Berry	OF106058	3 Dec 67	N/A
S-4	MAJ	Samuel P Muse	02014460	12 Dec 67	N/A
Signal	CPT	Walter G Hicks	05317127	14 Feb 68	N/A
A/C Maint	Maj	Brooks R Homan	01941366	15 Jan 68	5 Mar 68
	MAJ	Dale G Ruebsamen	01930234	5 Mar 68	TDY Eff 15 Mar
Safety	MAJ	Ronald J Sprengeler	091517	18 Dec 67	7 May 68
	MAJ	Willis B Anderson	0999030	6 Apr 68	N/A

- (3) (U) Subordinate Unit Commanders:
- (a) Commanding Officer Headquarters and Headquarters Company 307th Combat Aviation Battalion: lLT John F. Robb, 05536938, 15 January 1968 to 1 April 1968. CPT Jack D. Ragsdale Jr., 099235, 2 April 1968 to present.
- (b) Commanding Officer 199th Reconnaissance Airplane Company: Majer John S. Jacob, OF104822, 1 December 1967 to present.
- (c) Commanding Officer 221st Reconnaissance Airplane Company: Major James R. Mellish, 071229, 1 December 1967 to present.

- d) Commanding Officer 235th Armed Helicopter Company: LTC Floyd O. Eberhard, 088666, 1 June 1967 to 29 February 1968. Major Charles D. Gordon, 04030590, 29 February 1968 to present.
- (e) Commanding Officer, 244th Surveillance Airplane Company: Major James A. Bond, 099556, 31 January 1968 to present.
- d. (C) Unit Strength as of 30 April 1968 and Casualty Statistics for Quarter Ending 30 April 1968:
 - (1) (C) Military:

Subordinate Unit	Offi Auth	.ce t 0/H	WC Auth	0/H	Auth	O/H	Tot Auth	al <u>O/H</u>	WIA	<u>KIA</u>	MIA
199th RAC	22	30	1	2	97	99	130	131	1	0	0
221st RAC	42	38	1	1	123	104	166	143	2	0	1
235th AHC	15	16	42	30	214	209	271	255	9	4	0
244th SAC	17	28	22	1	323	351	362	380	22	3	2
HHC 307 CAB	18	10	3	1	188	75	109	87	1	Ō	0
52d QM Det	Q	0	0	0	8	21	8	21	0	0	0
307 CAB Tot	124	122	69	36	853	859	1046	1017	35	7	3

(2) (C) Civilians:

Subordinate	DA	C	V	N		Natl	
Unit	Auth	O/H	Auth	<u>0/H</u>	Auth	0\(\frac{1}{2}\)	Contractor
221st RAC	0	0	1	1	_0	0	0
307th CAB To	talO	0	1	1	0	0	0

- e. (U) Decerations Received for Quarter Ending 30 April 1968:
- (1) Distinguished Service Cross 1
- (2) Silver Star 2
- (3) Distinguished Flying Cross 9
- (4) Soldiers Medal 2
- (5) Bronze Star 7
- (6) Bronze Star with "V" 3
- (7) Air Medal 60
- (8) Air Medal with "V" 16

- (9) Army Commendation Medal 7
- (10) Army Commendation Medal with "V" 1
- (11) Purple Heart 41
- f. Aircraft Status as of 30 April 1968: (See Incl 2)
- g. Operational Support and Events:
- (1) (U) The reporting period began with units heavily committed in support of the IV Corps. The first of February was the third day of the VC initiated TET offensive. The three major airfields of Can Tho, Vinh Long and Soc Trang were attacked simultaneously on the night of 29 January 1968. Continuous pressure was applied to the airfields throughout the month of February 1968. The twelve stagefields, where this battalion has 0-1 aircraft stationed (Incl 4) in direct support of Province headquarters, were also attacked in much the same manner as the major airfields. The major attacks by the VC were normally initiated by mortar or recoilless rifle fire and followed by a ground attack. The VC did not attempt to follow through each attack with a ground assault but did follow through in enough instances with a ground probe so that considerable effort had to be expended to prevent the VC from finding a weakness in the defensive posture. The Viet Cong were fanatical in their attacks as was evident when documents captured during the attacks revealed that there were no plans for withdrawal and that popular support would be gained. The 235th Armed Helicopter Company was the deciding factor in silencing the indirect fire weapons employed against Can Tho City and Airfield. Armed Halicopters were the key to denying the three (3) major airfields in the Delta to the Viet Cong and immediately caused the coasation of the Viet Cong indirect fire weapons in every instance when an attack occurred. Fiercely fought ground attacks were repulsed by the 244th SAC and 235th AHC at Can Tho and the 199th RAC was instrumental in evicting an entrenched enemy from Vinh Long Airfield. Only light casualties were sustained. The month of March found pressure relieved upon the airfields and major population centers; however, harassing attacks with indirect fire weapons have occurred throughout the reporting period on an infrequent basis.
- (2) (U) The month of March, the battalion began the assumption of a supervisory role in the logistic management of the twelve (12) stage-fields throughout the Delta. The 164th CAG delegated the management of the pre-stock at the stagefields which must be maintained to insure airmobile operations can be sustained. To implement this change, the 52nd Quartermaster Detachment (POL) was assigned to the 307th Combat Aviation Battalion on 9 March 1968. The personnel of this detachment were further assigned to the Reconnaissance Airplane Companies and placed at each stagefield under the senior army aviator located at the

fields. This insures that the supervision of the stagefield and management of the POL and dispensing equipment is adequately controlled.

- (3) (C) The battalion, in the early part of March 1968, submitted to 6-2 IV Corps Advisor, a plan where by the strike capability of the battalion could be married up with the vast surveillance and reconnaissance abilities in the battalion. Numerous sightings and indications found by the eyes of the Delta, the 244th SAC (6V-1) Delta Hawks, the 197th RAC (6-1) Swampfoxes and the 221st RAC (0-1) Shotguns were compiled by intelligence agencies and revealed a vast intiltration network through which supplies were flowing to the VC from the Cambodian border unchecked.
- (a) (C) A night interdiction operation employing the concept of a light fire team of AH-IG (Cobras) and two (2) OV-1's (Mohawks) was initially tested. Under this concept, a free fire zone, in which a curfew was enforced, was established and an IR (OV-IC) Mohawk was dispatched followed by a Mohawk equipped with flares and the fire team of AH-IG Cobras. Upon the IR aircrafts finding a target, the flare ship dropped flares and the target was immediately engaged by the armed helicopters. This concept was highly successful but required instantaneous clearance to fire to prevent the loss of surprize gained from tring the electronic surveillance.
- (b) (C) The out growth of this initial concept of night interdiction was a day and night search and desthoy operation called the Delta Falcon. The results of this specific operation are as follows:

(Delta Falcon 5 March - 19 April 68)

VC KBA VC KIA POW'S	136 43 37
WIA	28
Individual Weapons Captured (Incl M3)	281
Ammunition Captured	26,564 168
Crew Served Weapons Captured	16
Anti-Aircraft Weapons Captured	16
Food Captured	nig no
Structures Destroyed/Damaged	224/102
Sampans Destroyed/Damaged	424/10
Oxen killed	13

This Delta Falcon Concept utilized all of the different assets of the battalion to seek out the enemy on his infiltration and commo-liaison routes and destroy him. The concept was employed in those provinces of the IV SRVN Corps which bordered the Canbedian border. Birddog (0-1) aircraft were sent out at first light to check known routes and areas where the night interdiction effort had been employed. The armed

helicopters were dispetched shortly afterword to check out the O-L sightings and confirm areas of probable activity by low level visual reconnaissance. On call at a staging area or an airborne check point were from 4 to 6 troop carrying helicopters with a ground element under the operational control of the Delta Falcon air mission commander. These troops were placed on the ground for very short periods of time at suspicious areas and areas engaged by the armed helicopters to search and evaluate the damage inflicted, capture supplies and gain all of the possible intelligence from these areas. The force was not to become engaged but was only to evaluate the situation for further exploitation by an airmobile force or ground attack. The ground element was make up of local Vietnamese troops thoroughly familiar with the area and normally the elite force of the provincial area. Because of the rapidity of the operation, numerous targets and sightings could be checked daily. The concept has evolved into a polished team of CV-1 and O-1 daylight ,ightings receiving prompt action by a strike force and then night sightings of the electronic surveillance aircraft being engaged immediately and evaluated, or if necessary; during daylight by the strike force.

- (c) (C) The success of the Delta Falcon concept has generated targets in excess of the strike capability of this battalion and the area of operation extended over distances which could not effectively be screened and the use of routes therein denied the enemy, Therefore, on 20 April 1968, "C" Troop, 7th of the 1st Air Cavalry Squadron was placed under the operational control of the Senior Advisor IV ARVN Corps to aid in the interdiction effort. The supervision of this OPCON unit has been delegated to the 307th Combat Aviation Battalion, and a gradual phase-in of the Cavalry Troop to assume the entire mission has been accomplished.
- (4) (C) The O-1 units have continued to provide the visual reconnaissance and surveillance in direct support of the sixteen (16) Province Headquarters and ARVN 7th, 9th, 21st Divisions and 44th Special Zone. The assignment of aircraft, locations and unit exercising operational control is portrayed in inclosure 4. The OV-1 unit has contributed heavily to the overall intelligence gathering effort in IV Corps and fully supported the Corps surveillance plan. The unit operates with the data processing capabilities consolidated at Can Tho which is the center of the Delta and headquarters for IV Corps. The Corps G-2 Air then evaluates and forwards the information to VN channels, to higher headquarters and down to the user level. The following statistics show the number of missions accomplished by the eyes of the Delta:

SORTIES FLOWN FROM 1 FEBRUARY TO 30 APRIL 1968

Type Acft	VR	Photo	IR	SLAP
0-1 0V-1	10,623 258	21 213	440	335
Total	10,881	234	440	335

- (5) (U) The 235th Armed Helicopter Company became the U.S. Army's first complete Huey Cobra gun company in late February and comparison of the AH-1G capabilities and missions with previous gunships is being evaluated. At present the AH-1G has been able to assume all of the typical missions previously handled by the older UH-1B/C model gunships. The availability rate of the aircraft has been less than the older model aircraft, but this stems from a shallow build up of PLI/ASL items and a high EDP rate for the aircraft.
- (6) (U) The Battalion has been successful in providing the necessary tactical combat support and direct combat support to IV ARVN Corps, the IV Corps MACV Advisory Group and U.S. Special Forces. The mission of the battalien is being accomplished daily. Statistics generated in support of these missions are in inclosure 3.
- 2. Section 2, Lessons Learned: Commanders Observations, Evaluations and Recommendations.
 - a. Persennel.

9

- (1) (U) Project Fix Personnel.
- (a) OBSERVATION. Personnel assigned to units on a 90 day TDY status greatly enhanced the maintenance effort of this battalion.
- (b) EVALUATION. The personnel selected for the 90 day loan period from CONUS to in-country units provided the man hour difference that was needed to cope with the increased guard and maintenance hours created by the TET effensive. The majority of the personnel assigned were combat veterans of previous tours in Vietnam and the experience level far surpassed the normal replacement personnel. There was no morale or disciplinary problem involved with these enlisted men and the general military attitude of, "There is work to be done and we can do it," prevailed for the entire 90 day period. The only significant problem area associated with these personnel was that the battalion didn't know they were coming and initially a shortage of some items of organizational equipment were not available (e.g., rifles, steel helments, flak vests, protective masks and cots).
- (c) RECOMMENDATIONS. This technique should be retained as an adequate method of augmenting over committed units in any theater of eperation. Should this method of augmentation be employed in the future, a means of outfitting individuals with necessary organizational equipment should be programmed in the planning phase.
 - b. Operations.
 - (1) (U) Evacuation of Aircraft.

- 10
- (a) OBSERVATION. Pricr planning of evacuation of aircraft because of weather or enemy action must be accomplished to insure safety of operation and control.
- (b) EVALUATION. During the TET offensive aircraft were ordered to be evacuated numerous nights from base airfields to alternate airfields. Sometimes after arriving at the safe haven airfield, it was determined the threat was just as great there. Normally there would be inadequate facilities such as no revetments or POL pumps available. In addition to the evacuation of aircraft to other airfields, an alternate method of orbiting aircraft during periods of increased threat was accomplished. This latter method must involve very close coordination to insure all aircraft do not return at the same time and become vulnerable to attack while refueling or parking. The orbiting of aircraft is a poor solution in that an excessive amount of flying time is put on a fleet of aircraft when maintenance is at a critical print. An evaluation of the risk of damage that can be inflicted and repaired in a certain time frame versus the number of hours of maintenance to repair and maintain the extra flying hours established by orbiting must be made.
- (c) RECOMMENDATION. That the planning for evacuation of aircraft be made at the highest level which can evaluate the total enemy threat and total facilities available. If the decision not to evacuate but orbit is made, the responsibility to plan and execute must rest with an installation or unit commander at a lower level to insure that the proper coordination of minute details are accomplised.

(2) (U) Flight Following.

- (a) OBSERVATION. Specific flight fellowing precedures must be adhered to for units that place enteraft under OPCON to activities and Army elements that aperate independently in remote areas with no flight fellowing facility.
- (b) EVALUATION. This battalion lost an aircraft that was supporting a Special Forces operation and the fact that the aircraft was missing was not fully realized until 48 hours later. Immediate search and rescue operations were not conducted. The aircraft was not located, even though an extensive search was made for 72 hours of the alleged area. Forty seven days later, a member of the crew was able to escape from his captor and give the details of being shot down. The area that the aircraft was down in had been searched but had there been positive control or flight following, the whereabouts of the aircraft might possibly have been known sooner.
- (c) RECOMMENDATION. Pilota on independent missions in support of special activities must follow the established flight following precedures and in addition have the activity that is being supported assume some

responsibility to check and insure they know the ETD and ETA for all missions. This is a cardinal rule which aviators cannot ignore and is of paramount importance to insure search and rescue is activated promptly.

c. Training!

- (1) (U) Jungle Environmental Survival Training Course and PACAF Jungle Survival School.
- (a) OBSERVATION. School quotas should be made available for crews of AH-1G helicopter to attend survival courses.
- (b) EVALUATION. At the present time quotas for attendance at above listed schools are primarily for OV-1 and O-1 crews. This battalian has sent 30 personnel to these two courses in the last 90 days. The AH-1G operates independently here in the Delta and in many cases as a team with the OV-1. Because of the manner of operation, the AH-1G crews are as susceptible to being forced down in uninhabited areas and the jungle as the fixed wing aircraft in the battalion.
- (c) RECOMMENDATION. That the quotas for the survival schools be increased to enable more personnel to attend from AN-1G units without decreasing the quotas for assigned fixed wing units.
 - d. Intelligence. None
 - e. Logistics.
 - (1) (U) Ammunitien 7.62, Type A-165.
- (a) OBSERVATION. Excessive number of stoppages for number of rounds fired occur when utilizing the 7.62 ammunition pre-linked in 200 round boxes and excessive ground time for loading.
- (b) EVALUATION. The boxes of 7.62 ammo when linked by hand inte 1000 round belts cause an unnecessary delay and waste in combat manpower. The solution to this problem is issuance of the type A-165, 7.62 ammunition which comes in longer belts. This is not the only problem with the standard M-60, 7.62 ammunition. The stoppage rate is greater with the M-60 ammunition when compared to the type A-165 ammunition. Even though USA WECOM personnel in CONUS state there is no manufacturing difference, the results indicate otherwise. The stoppage rate has been 1:11,150 rounds fired for the M-60 ammunition versus 1:23,230 rounds fired for type A-165 or double the stoppages when using the standard M-60 ammunition.
- (c) RECOMMENDATION. Recommend the procurement of the Type A-165 ammunition be expadited. This is the second time this recommendation has

(2) (U) Improper Oil in O-1 Aircraft.

- (a) OBSERVATION. Recently two (-1.'s of this unit suddenly started to burn excessive oil with no prior indications of high oil consumption.
- (b) EVALUATION. An extensive technical inspection of the aircraft indicated that both aircraft had been serviced with USAF high detergent eil, Mil-I-6082B with Cyclo Hexanone. The proper oil for the Army 6-1 is LAD II, Mil-22851, Type II. The high detergent oil will cause excessive all consumption in the 0-1 aircraft after it has been using the proper oil. The marking on the drums as listed above is the only identifying characteristic to keep these oils separated. An education process in necessary for crewmen servicing 0-1 aircraft and for POL personnel to keep the oils identified separately as detergent and nendetergent in the POL storage areas.
- (c) RECOMMENDATION. That this information be republished for all users of the 0-1 aircraft and that the minimum precautions taken by this battalion be required for users of the 0-1 aircraft.

(3) (U) Additional Beacon Light for 0-1 Aircraft.

- (a) OBSERVATION. Flight tests show that the lower mounted beacon on the O-1 aircraft is not visible unless the intercepting aircraft is below a line 120 inches above the horizontal reference datum.
- (b) EVALUATION. The obvious solution to the problem was the installation of an upper anti-collision beacon. Three types of beacons were tested and two proved to be satisfactory. The light, recognition, aircraft manufactured by Whelen Engineer Company was found to be unsatisfactory due to downward light patterns which flooded the cockpit with light. The "low Drag" oscillating beacon and the "Twin Bulb" beacon, both manufactured by Grimes Incorporated, reflect upward patterns of light and are satisfactory to use as an upper anti-collision light. It should be noted that the present circuit breaker in the 0-1 is capable of providing power for both beacons. The light should be installed between and directly to the rear of the two right front upper observation windows. One small piece of aluminism tape is required on the dome to prevent glare on the prop.
- (c) RECOMMENDATION. That authority be granted to install this additional beacen and all 0-1 aircraft and users be advised of the limitations of the present beacon.

(4) (U) Red Light For 0-1 Instrument Panel.

- (a) OBSERVATION. The present fluorescent light on the O-1 aircraft causes a diffusing of light on the plexi-glass windshield and prevents effective night visual reconnaissance.
- (b) EVALUATION. During night operations in Vietnam, extreme black out conditions prevail and the bright glow from the fluorescent lights even when on the lowest intensity restricts outside vision. This glow is also very fatiguing on the eyes. Another fault this system has is the unsafe condition experienced when the throttle is moved forward (O-1D) and blocks the light from the airspeed indicator. A solution has been found by mounting the post type red instrument lights from salvaged UH-1 helicopters and wiring these in with the present rheestat for the O-1 radio switches. An EIR has been forwarded on this item.
- (c) RECOMMENDATION. That the EIR preprinted Control Number, F-73747 be approved and an MWO be forwarded to 0-1 units expeditiously.
 - (5) (U) AH-1G Attitude Indicator.
- (a) OBSERVATION. The replacement attitude indicator for the AH-1G has proven as unsatisfactory as the original installed equipment.
- (b) EVALUATION. The reliability of the new Bendix attitude indicator is unacceptable. The pillets of the unit cannot place full confidence in the attitude indicator and this hesitancy on the part of the pilets to fly what is alleged to be an all weather day and night helicopter detracts from mission performance. Flights at night without a visible horizon and target attacks at night with the resultant muzzle flash-back and momentary discrientation have forced the aircraft to maintain a higher altitude and restricts some night visual reconnaissance missions. Neither the cld Bendix (Part Nr 209-C70-116-3) nor the new Bendix (FSN 1560-782-0083) Attitude Indicators are reliable.
- (c) RECOMMENDATION. It is imperative that a reliable attitude indicator be provided for the AM-IG helicopter and tested prior to issuance to operational units.
 - (6) (d) Excessive NORS Rate for AH-1G's.
- (a) OBSERVATION. This unit averages 50% of its assigned AH-1G helicapters in an (EDP) NORS status.
- (b) EVALUATION. This battalion has one armed helicopter company of 22 assigned AH-1G helicopters on hand. The present ED? rate is unacceptable for perfermance of assigned missions. The supply system has not been able to cope with the demands of this unit even though the aircraft flying hours are below the USARV flying hour program. The aviation tech supply of this company has 1700 separate demands in an open reconciled

status with its Direct Support Maintenance facility. Continued delay in providing parts presently on requisition will only increase the EDP rate.

- (c) RECOMMENDATION. That immediate action be taken to provide the necessary supply of AH-1G helicapter parts and that stockage of the items be maintained at all echelons to support combat mission requirements.
 - (7) (U) Test Stand, Hydraulic.
- (a) OBSERVATION. The current Aircraft Field Maintenance tool set of the 235th Armed Helicopter Company does not provide the necessary equipment to properly maintain the AH-1G helicopter.
- (b) EVALUATION. There is no item of equipment in the present TOE or tool sets which would enable the maintenance personnel to calibrate and trouble shoot the Stabilization Augmentation System or the Armament Subsystem on the AH-IG. At the present time testing and trouble shooting on the subsystems can only be performed when the aircraft is run up. When the aircraft teannet be run up a work stoppage occurs when otherwise a complete check of the subsystem could have been made, and the aircraft would be mission ready when the first run up is accomplished.
- (c) RECOMMENDATION. That immediate procurement of a Test Stand, Hydraulic (FSN 4920-141-8801) be authorized units maintaining the SAS and Armament Subsystems on the AH-1G helicopters. (Voucher Number of Requisitioned Item is AT 8152-8046-4172 BO6 with the 490th Gen Spt Company, Vung Tau, RVN.)
 - f. Organization.
 - (1) (U) Armed Helicopter TO&E.
- (a) OBSERVATION. The present TO&E (1-77) with MTOE does not previde for the personnel or equipment to support an armed helicopter company.
- (b) EVALUATION. There are no ammunition handlers and storage personnel (55B) assigned to aid in the tremendous volume of ammunition used by the AH-1G helicopters. The unit TOKE does not provide for an adequate number of personnel to maintain and repair the armament subsystems on the AH-1G. At present there are only three TOKE positions authorized under the MTOE for TOKE 1-77 in the armament repair MOS of 45J2Q. Vehicles to transport the ammunition to the aircraft for actual loading are lacking and at present only one 3/4 ten truck with trailer is authorized per flight platcon. The authorization of six 1/2 ten (Army Mule) trucks platform, utility, M-27485 (FSN 2323-937-1976), two per plateon, would provide the capability to move ammunition from unit storage areas to the aircraft. Ammunition can be fed into the systems

15

direct from the platform of these trucks. In addition this vehicle can be moved to forward staging areas by the helicopter transporting the ground element, thus giving the ground element a transporter for ammunition without having to rely on aid from the support unit. These major areas of the TOE for an armed helicopter company have been submitted for revision through appropriate channels along with other changes.

(c) RECOMMENDATION. Recommend that a specifically tailored TOE for an armed helicopter company be established or an adequate MTOE be implemented at the earliest practicable date. This is the second time this recommendation has been made on an ORLL.

g. Other.

- (1) (U) Additional Protection for Wounded Aviators.
- (a) OBSERVATION. By placing two ammonia aromatic ampuls in a standard U.S. Army pill bottle affixed to the instrument panel of an 0-1, the pilot has easy access to the stimulant.
- (b) EVALUATION. Two wounded 0-1 pilots found that they nearly passed out from pain and the sight of their own blood after being wounded. Neither pilot had an observer and both pilot's wounds were in such a position as to preclude their getting to the aircraft's first aid kit. Neither pilot fainted, but both stated they were very weak. By placing two of the ammenia inhalents where the pilot has easy access to them, he can break one and provide himself with the necessary stimulant to revive himself sufficiently to make a satisfactory landing.
- (c) RECOMMENDATION. That the above lessen learned be passed to other aviation units as a means of increasing the chance of pilot survival.

CHARLES F. HUTCHINS

LTC; Armor Commanding

AVCN (15 May 1968) 1st Ind SUBJECT: Operational Report of 307th Combat Aviation Battalion for the Period Ending 30 April 1968, RCS CSFOR-65 (RI) (U)

Commanding Officer, 164th Aviation Group, APO San Francisco 96215, 28 May 68

TO: Commanding General, 1st Aviation Brigade, ATTN: AVBA-C, APO 96384

- 1. (U) The attached 307th CAB ORLL for the period ending 30 April 68 has been evaluated as required by USARV Reg 525-15.
- 2. (U) The following comments on <u>Section 2. Lessons Learned: Commanders</u>
 Observations Evaluations and Recommendations, are submitted.
- a. <u>Project Fix Personnel</u>: Project fix personnel were a marked asset to the entire command. Sufficient organizational equipment to equip each individual was available within the group. This equipment was quickly redistributed each individual was equipped with the necessary items within three days after attachment.
- b. Evacuation of Aircraft: The evacuation of aircraft during the Tet Offensive was successful. Concur with the requirement for adequate planning.
- c. Flight Following: Current flight following procedures are considered adequate when utilized. Proper flight following is a subject of continuing emphasis in this command.
- d. Jungle Survival Training: It is recognized that jungle survival training is beneficial to all aviators flying in Vietnam. Priority for attendance should remain with OV-1 and O-1 crews. The AH-1G normally operates in a team of more than one aircraft. An AH-1G crew is more likely to be recovered quick than O-1 or OV-1 crews.
- e. Ammunition 7.62. type A-165: This item has been submitted in a previous ORLL, and was improperly included in this report.
- f. Improper Oil in O-! Aircraft; This is not a new problem. Current publications specify the correct oil to be used in all engines. Segregated storing procedures are habitually employed in most aviation units. No further dissimenation is considered necessary.
- g. Additional Beacon Light for 0-1 Aircraft: Concur with the recommendation. Additional rotating beacon will contribute to safer operations.
- .h. Red Light for 0-1 Instrument Panel: Concur. This has proved to be a satisfactory solution to the inadequate night lighting for the 0-1 instrument panel.

AVGN
SUBJECT: Operational Report of 307th Combat Aviation Battalion for the Period Ending 30 April 1968 RCS CSFOR-65 (RI) (U)

- 1. AH-1G Attitude Indicator: Concur with the recommendation. An EIR has been submitted.
- j. Test Stand Hydraulic! Concur with the recommendation. A requisition and a letter requesting authorization for the test stand have been submitted.
- k. Armed Helicopter TOKE: Concur with the recommendation. An MTOE for the 235th Armed Helicopter Company has been submitted. The 235th AHC is now augmented with vehicles and personnel from other group assets.
- 1. Additional Protection for Wounded Aviators: Concur with the recommendation.
- 3. (C) Excessive NORS Rate for AH-1G's: Concur with the recommendation as stated. Appropriate follow-up action on requisitions has been initiated at all levels within this command.

ROBERT L. McDANIEL Colonel, Infantry

Commanding

AVBA-C (15 May 68) 2d Ind

SUBJECT: Operational Report of 307th Combat Aviation (Phantom) Battalion for Period Ending 30 April 1968, RCS CSFCR-65 (R1) (U)

DA, HEADQUARTERS, 1ST AVIATION BRIGADE, APO 96384 JUN 27 1968

THRU: Commanding General, United States Army Vietnam, ATTN: AVHGC-DST, APO 96375
Commander in Chief, United States Army Pacific, ATTN: GPOP-OT, APO 96558

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

- 1. (U) This Headquarters has reviewed this report, considers it to be adequate, and concurs with the contents as indorsed.
- 2. (C) The following additional comments are considered pertinent:
- a. Paragraph 2c(1), page 9. Quotas for attendance to the survival schools are allocated from Brigade to Groups on as equitable a basis as possible. Brigade policy places priority of allocation to the units with the most cogent need for survival training, therefore the OV-1 and O-1 companies are given first priority due to the type single ship missions they perform. Priorities then go to the Assault Helicopter Companies and Assault Support Helicopter Companies. There is nothing to preclude Groups and Battalians from allocating quotas to lower priority units as the need exists. The Brigade goal is to provide a school trained Escape and Evasion Officer to each unit in order to pass on to others the benefits of his formal training. On 12 June 1968, USARV allocated additional quotas to the Air Force Sea Survival School. It is anticipated that Sea Survival School quotas will go to OV-1 units, thus providing Jungle Survival School quotas to other units with lower priority.
- b. Paragraph 2e(1), page 9. It is accepted as a general fact that the Al65 is superior to the Al31 7.62mm linked ammunition. Al65 will possibly be removed from control by allocation on an ASR by the end of June 68 which will make it more readily available to the unit.
- c. Paragraph 2s(3), page 10. Concur with observation. The recommendation that authority be granted to modify the aircraft should be considered by USAACOM. 1st Aviation Brigade Headquarters will recommend that units with 0-1 aircraft submit Equipment Improvement Recommendations if they consider this to be a serious problem.

AVBA-C

SUBJECT: Operational Report of 307th Combat Aviation (Phantom) Battalion for Period Ending 30 April 1968, RCS CSFOR-65 (R1) (U)

d. Paragraph 2f(1), page 12. This Headquarters has initiated action to prepare a standardized MTOE for the Armed Helicopter Company which should resolve the problems as stated in this ORLL.

FOR THE COMMANDER:

JOHN D MIXSELL, JR.

CPT, AGC

Assistant Adjutant General

AVHGC-DST (15 May 68) 3d Ind (U) CPT Arnold/ms/LBN 4485 SUBJECT: Operational Report of 307th Combat Aviation (Phantom) Battalion for Period Ending 30 April 1968, RCS CSFOR-65 (RI)(U)

HEADQUARTERS, US ARMY VIETNAM, APO San Francisco 96375 2 9 JUN 1968

TO: Commander in Chief, United States Army, Pacific, ATTN: GPOP-DT, APO 96558

- 1. This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 30 April 1968 from Headquarters, 307th Combat Aviation (Phantom) Battalion.
- 2. Concur with report as submitted.

FOR THE COMMANDER:

C. S. NAKATSUKASA
Captain. AGC
Assistant Adjutant General

Copies furnished: HQ, 1st Avn Bde HQ, 307th Cmbt Avn Bn GPOP-DT (15 May 68) 4th Ind (C)
SUBJECT: Operational Report of HQ, 307th Cbt Avn (Phantom) for Period
Ending 30 April 1968, RCS CSFOR-65 (R1)

HQ, US Army, Pacific, APO San Francisco 96558 23 AUG 1368

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310


- 1. (U) This headquarters has evaluated subject report and forwarding indorsements and concurs in the report as indorsed.
- 2. (C) The following additional comments are pertinent:
- a. Reference (page 10) paragraph 2e(3): Additional beacon light is justified for O-1 aircraft in the interest of flying safety. Since it appears that this modification can be made without extensive reconfiguration of the aircraft or aircraft components, it should be authorized without delay. O-1 aircraft in Vietnam frequently operate at night in areas of high traffic density. The cost of this proposed modification compared to the cost in equipment and lives resulting from mid-air collisions is negligible.
- b. Reference (page 12) paragraph 2f(1): The MTOE for the Armed Helicopter Company is adequate when the company is equipped with UH-1B/C aircraft. When the aircraft authorized these companies is changed to the AH-1G, a change in support, personnel, and equipment should be effected. This has not been the case in units in Vietnam. Consequently, the effectiveness of these units is seriously impaired. Future conversions of Armed Helicopter companies should include such consideration.
- c. Reference 2d Indorsement, paragraph 2b: Increased production has allowed A-165 to be removed from control by allocation on ASR. Therefore, the stated problem no longer exists.

FOR THE COMMANDER IN CHIEF:

C.R. SHORTT CPT, AGC Asst AG

Cy furn: CG USARV





Incl 1

24

307th Cbt Avn Bn AIRCRAFT STATUS 30 April 1968


2	E	н/а≀-но	AH-1G	10	OV-1A	1A	0V-1B	.1B	07-10	-10	9	0-16	9	Q-10	5	U-6Å
TIMI	AUTH	н/о	AUTH	н/о	о/н аптн	0/н	AUTH	0/н	AUTH	0/н	AUTH	0/н	AUTH	0/н	HILO	н/о
199th Ric											72	12			0	-
221st RAC													26	38	0	•
≥ 235th AHC	3	7	21	R												
					0	2	9	7	12	10					0	-
HHC 307th CAB	2	0													0	-
. 307th CAB	150	7	র	8	0	8	9	7	12	10	24	27	32	88	0	7

Incl 2

307th Cbt Avn Bn OPERATIONAL STATISTICS QUARTER ENDING 30 April 1968

		#	HOURS FLOWN	TOWN			STRUCTURES	WRES	SAMPANS	ANS	AIRC HIT GRND	AIRCRAFT HIT BY RND FIHE	AIRCRAFT CONFIRMED	VAFT	AIRCRAFT	ZAPT
UNIT	SORTIES	FEB	MAR	APR	TOTAL	ENEMY	DAM	DEST	DAM	DESI	30CAL 50CAL		CMBT	CMBT	SSOI	DAM
199th RAC	10275	2633	2633 24.28	2088	7149	326	181	255	192	150	38	1	(E)	(39)	Eī	3
221st RAC	8104	2873 2971		2857 8701	8701	217	165	152	143	171	877		(1)	(59)	1	(2)
235th AHC	5537	1954 1609		1125	8897	1222	1173	1373	630	808	99	2	(1) UH-1C	(5) UH-E (70) AH-G	ı	(2) AH-1G
244th SAC	1302	793	876	852	2521	ı	ı				14	8	ı	(16) 0V-1	(2) 0V-1	347
HHC 307th CAB	647	115	159	138	453	ı	ı	ı	1	-	•	ı				ı
307th CAB	25865	8368		7101	8043 7101 23512	1765	1819	1780	965	1127	166	11	3	189		9

Incl 3



Incl 4

DOCUMENT CO	NTROL DATA - R	& D
(Socurity classification of title, body of abstract and index	ing annotation must be e	entered when the overall report is classified)
1. ORIGINATING ACTIVITY (Corporate author)		Confidential
HQ, OACSFOR, DA, Washington, D.C. 20310		zb. GROUP
I. REPORT TITLE		
Operational Report - Lessons Learned,	Headquarters,	307th Combat Aviation Battalio
4. DESCRIPTIVE NOTES (Type of report and Inclusive dates) Experiences of unit engaged in countering 5. AUTHOR(5) (First name, middle Initial, last name)	surgency opera	ations, 1 Feb - 30 Apr 1968
CO, 307th Combat Aviation Battalion		
. REPORT DATE	78. TOTAL NO. OF	F PAGES 76. NO. OF REFS
15 May 1968	24	
M. CONTRACT OR GRANT NO.	M. ORIGINATOR'S	'S REPORT NUMBER(S)
b. PROJECT NO.	682	2185
e. N/A	9b. OTHER REPOR	ORT NO(3) (Any other numbers that may be assigned
d.		
10. DISTRIBUTION STATEMENT		
11. SUPPLEMENTARY NOTES	12. SPONSORING	MILITARY ACTIVITY
N/A	OACSFOR, DA	A, Washington, D.C. 20310
13. ABSTRACT		
	24	
DD FORM 1473	UN	NCLASSIFIED

Security Classification

ITEM 1	
* SUBJECT TIT	LE
***PAGE #	
ITEM 2	
SUBJECT TIT	LE
FOR OT RD #	
PAGE #	
ITEM 3	
SUBJECT TIT	LE
FOR OT RD #	
PAGE #	
ITEM 4	
SUBJECT TIT	LE
PAGE #	
ITEM 5	
SUBJECT TIT	LE
PAGE #	
* Subject Titl of interest.	e: A short (one sentence or phrase) description of the

***Page # : That page on which the item of interest is located.

- -FOLD - -

DEPARTMENT OF THE ARMY

POSTAGE AND FEES PAID
DEPARTMENT OF THE ARMY

OACSFOR Washington, D.C. 20310

Hqs, DA, OACSFOR
Operational Reports Branch
Rm 3B466
The Pentagon
Washington, D.C. 20310

STAPLE

DA fabel 18, 1 Apr 80 PREVIOUS EDITIONS OF THIS LABEL ARE OBSOLETE.

16-78613-1

- - -FOLD -